	Format	No: ER 5/10– F2,	JOB SAFE	TY ANALYSIS (JSA)	, IB THERMAL POW	ER STATION, OPGC			
Serial No.	Department	Equipment	Location	Job description:					
	Facility Management		ITPS colony	AMC for Civil Maint	tenance Jobs in ITPS C	olony 2025-27			
JSA performed by:	Signature	Reviewed &	Signature	Date of Issue	Date	e of revision		Revision No-	
		Approved by							
			HAZARD TE	XT/TYPE ( For refere	ence to identify the Ha	azard type )			
PHYSICAL HAZARDS	PHYSICAL HAZARDS	PHYSICAL HAZARDS	ELECTRICAL	CHEMICAL/ GAS	EX	CAVATION	OTHERS		
			HAZARDS	HAZARDS					
Noise	Fall from height	Force (Push/Pull)	Shock/	Flammable/	Collapse/Sliding		Fire		
			Electrocution	Explosive					
		_		substances					
Radiation	Fall (Slip/Trip)	Caught in/on or	Static	Inhalation of toxic	Underground live cal	ole damage	Heavy Wind/Rain		
- 4		between	electricity	fumes					
Confined space	Fall down/below	Struck by/against	Arcflash/ blast		ERGONOMICS		Dust exposure		
F	Full of Obligate Const	E tours and to	DIOLOGICAL	ion	December 1		0111		
Exposure to	Fall of Objects from		BIOLOGICAL	Body/Eye Contact	Poor Posture		Oil spill		
pressurised	height	(Hot/Cold)	HAZARDS						
Steam/Air Contact with Hot	Contact with	Poor illumination	Snake/Insect	Spillage	Repeatative motion		Human factor		
		Poor illumination	bite/Virus	Spinage	Repeatative illotion				
surface	moving parts		infection						
PPEs to be used Safety shoes, hand gloves ,safety helmet, Nose mask, Ear plug/muff, Safety goggles, reflective vest, etc.									
Tools required							x, measuring tape, plumb bol	o. sand screen, spade.	
•		trol measures, consider				, ,	, 8	, ,	
SEQUENCE OF		SAFETY, HEALTH &				/ HAZARD CONTROL MEASU	JRES	Are control	
		HAZARI	os	Elimination/	Engineering	Administrative	PPE	Measures adequate	
				Substitution				to mitigate the risk	
								(Yes/No)	
								' '	
6 11 .1		-1						.,	
Excavation for plinth,	drains, flooring and	Electrocution/Shock fr				Ensure the proper isolation	-	Yes	
brick work.		underground/burried	cables			and put local LOTO on the	,safety helmet, safety		
						RCCB/Main switch. Ensure			
						zero voltage before starting	plug/muff		
						the job. Use insulation mat			
						while doing isolation.			
-		Body injury (Slip/trip)				Have a 360 degree vision	Safety shoes, hand gloves	Yes	
		[ (Silp) (Tip)				and be alert about the area	-		
						of work. Use proper and	goggles, nose mask, ear		
						healthy tools.	plug/muff		
						ineartify tools.	piag/ illuli		
						1			

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEP	S / HAZARD CONTROL MEAS	JRES	Are control	
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)	
	Body eye conact/ hand/leg injury while digging/manual excavation			Engage inline experienced work person, Use healthy and tested Tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about	Safety shoes, hand gloves	Yes	
	Collapse/sliding of soil			Keep the excavated soil at a distance of 1 mtr from the excavated pit/trench. Barricade the area of work.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear		
	Dust/Ash/fumes			Keep dust/fume mask with you. Use wherever needed.Check, whether the filters of the mask are clean before using. Use clean	,safety helmet, safety goggles, nose mask, ear	Yes	
	Fall of person inside excavated pit/trench			Barricade the working area with hard barrication. Use caution tapes and barriers wherever required.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
Backfilling/ plinth filling .	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves	Yes	

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		JRES	Are control		
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Dust/Ash/fumes			Keep dust/fume mask with you. Use wherever needed.Check, whether the filters of the mask are clean before using. Use clean	,safety helmet, safety goggles, nose mask, ear	Yes
Concrete work for plinth, drains , flooring and PCC for foudation.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff, gum boots.	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use rubber hand gloves to avoid direct contact with cement.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff, gum boots.	Yes
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff, gum hoots	Yes
Centering and shuttering work for slab,beam, coloumn,lintels etc	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		Are control			
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Falling from height of workmen		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of scaffolding, ensure height work permit.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
M.S. Reinforcement bar cutting, binding and placing for beam, coloumn, slab, lintel.	Electrocution			Ensure the insulation of reinforcement cutting machine and its cable. Ensure that the power source is from a 30mA	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Falling of Object from height		4 of 16	Proper supervision to be done, restrict unauthorized entry to the workplace, ensuring height work	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

Page 4 of 16

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		Are control			
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Noise from cutting machine			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes
Cement plaster/ punning (finishing work) for plinth drain and flooring	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use rubber hand gloves to avoid direct contact with cement.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes
Repairing of ceiling plaster.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		JRES	Are control		
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Falling of workmen from height		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of platforms, ensure that top rail and midrails are healthy and strong.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
			Remove all ceiling fans before starting the job.	Ensure that the rungs are not damaged. Have a clear vision of the area before climbing, to avoid hitting hanging objects.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
Brick work for foundation and superstructure.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS	S / HAZARD CONTROL MEAS	JRES	Are control	
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace.	Safety shoes, hand gloves	Yes	
	Falling of workmen from height		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of platforms, ensure that top rail and midrails are healthy and strong.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
Dismantling of brickwork and cement concrete	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves	Yes	
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace.	Safety shoes, hand gloves	Yes	

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS / HAZARD CONTROL MEASURES				
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)	
Fixing of floor tiles , wall tiles, kodappa, granite stone, marble stone.	Electrocution			Ensure the insulation of tile cutting machine and its cable. Ensure that the power source is from a 30mA sensitive RCCB	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Dust/Ash/fumes			Keep dust/fume mask with you. Use wherever needed.Check, whether the filters of the mask are clean before using. Use clean	,safety helmet, safety goggles, nose mask, ear	Yes	
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Noise from cutting machine			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear nlug/muff	Yes	

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS / HAZARD CONTROL MEASURES					
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)		
Making and fixing of wood choukhat for doors and windows.	Electrocution			Ensure the insulation of wood cutting machine and its cable. Ensure that the power source is from a 30mA sensitive RCCB.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes		
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes		
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes		
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace, ensuring height work	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes		
	Falling of carpenter from platform			Use certified platforms, ensure that top rail and midrails are healthy and strong.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes		
	Noise from cutting machine			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes		
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear nlug/muff	Yes		

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS / HAZARD CONTROL MEASURES				
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)	
Making and fixing of wood pannel shutter for doors and windows.	Electrocution			Ensure the insulation of wood cutting machine and its cable. Ensure that the power source is from a 30mA sensitive RCCB.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Falling of carpenter from platform			Use certified platforms, ensure that top rail and midrails are healthy and strong.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes	
	Noise from cutting machine			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
Priming & painting of wall and ceiling.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS	6 / HAZARD CONTROL MEASU		Are control	
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)	
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools.Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes	
	Falling of workmen from height		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of platforms, ensure that top rail and midrails are healthy and strong.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	
				Ensure that the rungs are not damaged. Have a clear vision of the area before climbing, to avoid hitting hanging objects.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes	

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS	S / HAZARD CONTROL MEASU	JRES	Are control  Measures adequate to mitigate the risk (Yes/No)
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	
Repair of M.S doors / grills/ shutters	Electrocution			Ensure the insulation of grinding and steel cutting machine and its cable. Ensure that the power source is from a 30mA	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Inhalation of toxic fumes			Use good quality nose mask.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear olug/muff	Yes
	þ			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace, ensuring height work	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT	SAFE JOB STEPS / HAZARD CONTROL MEASURES				Are control
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Fire hazard			Remove any combustible subastance from the fabrication yard. keep fire extinguisher and water &sand bucket at site.Ensure hot work permit before starting of job.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
Fixing of GCI and colour coated sheets	Electrocution			Ensure the insulation of grinding and steel cutting machine and its cable. Ensure that the power source is from a 30mA	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Noise from drill machine			Use good quality ear plugs/muffs. Take rest in between the job. Do not expose yourself to	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Falling of Object/ tools from height			Proper supervision to be done, restrict unauthorized entry to the workplace, ensuring height work	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT HAZARDS	SAFE JOB STEPS / HAZARD CONTROL MEASURES				Are control
		Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Falling of workmen from height'		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of platforms, ensure that top rail and midrails are healthy and strong.	,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
Errection of Pipe scaffolding and aluiminium scaffolding for working at height.	Falling of workmen from height		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Use A-type FRP Ladder and one person must be holding the ladder at the time of climbing/decending. Have a firm grip on the ladder/platform and maintain a 3-point contact while climbing/decending on the ladder/platform. In case of scaffolding, ensure height work permit.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Fall of ladder/platform		Ensure that the ladder/platform should be placed on a flat and rigid surface.	Ensure healthiness of ladder and its rungs before work. The ladder/platform should be placed on a flat and rigid surface.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT HAZARDS	SAFE JOB STEPS / HAZARD CONTROL MEASURES				Are control
		Elimination/ Substitution	Engineering	Administrative	PPE	Measures adequate to mitigate the risk (Yes/No)
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
Removing of construction debris.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves	Yes
	Body eye conact/ hand injury			Engage inline experienced work person, Use healthy and tested Tools. Use safety goggles to avoid any foreign material to go inside your eye.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Dust/Ash/fumes			Keep dust/fume mask with you. Use wherever needed.Check, whether the filters of the mask are clean before using. Use clean	,safety helmet, safety goggles, nose mask, ear	Yes
	Falling of Object from height			Proper supervision to be done, restrict unauthorized entry to the workplace.	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Poor Posture			Take Rest in between the job. Do not overstrech your body. Keep in mind about your body limits.	Safety shoes, hand gloves	Yes
Tractor loading and unloading for shifting of materials at site.	Body injury (Slip/trip)			Have a 360 degree vision and be alert about the area of work. Use proper and healthy tools.	Safety shoes, hand gloves	Yes

SEQUENCE OF BASIC STEPS	SAFETY, HEALTH & ENVIROMENT	FETY, HEALTH & ENVIROMENT SAFE JOB STEPS / HAZARD CONTROL MEASURES				
	HAZARDS	Elimination/ Substitution	Engineering	Administrative	PPE	Are control Measures adequate to mitigate the risk (Yes/No)
	Body eye conact/ hand injury			work person, Use healthy and tested Tools.Use safety	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Dust/Ash/fumes			Keep dust/fume mask with you. Use wherever needed.Check, whether the filters of the mask are clean before using. Use clean	,safety helmet, safety goggles, nose mask, ear	Yes
	Falling of Object from height			Proper supervision to be done, restrict unauthorized	Safety shoes, hand gloves ,safety helmet, safety goggles, nose mask, ear plug/muff	Yes
	Poor Posture			job. Do not overstrech your body. Keep in mind about	Safety shoes, hand gloves	Yes
Emergency Safety Measures ( Rescue/Fi	re Brigade etc):	Emergency Contact	s-Main Control Roon	n- 222, 233,244, Fire- 777, 222	257, Ambulance- 248/337, F	lospital-666
Overal Job Risk Category-	HIGH					
JSA Review during PJB:						
Pre Job Briefing (PJB) is applicable to all						
	: I undertake that the JSA is communicate	d to me effectively				
Name	Agency's name			Signature		
		<u> </u>				