ODISHA POWER GENERATION CORPORATION LTD IB THERMAL POWER STATION

BANAHARPALLI

HAZARD IDENTIFICATION & RISK ASSESSMENT (OCCUPATIONAL HEALTH & SAFETY)

Name of work :Development of ash dyke for emergency disposal of bottom ash

FORMAT NO: ER 5/10-F1

FO	RMAT REVISION NO:	DOCUMENT REVISION		DOCUMENT REVIS	SION DAT	E: 10.08.18						Г
							Qualitative C	riteria	Quant	itative Cr	iteria	
SI. No.	Responsible Deptt.	Activity	Description of Hazard	Risk	Routine/Non-Routine(R/NR)	Existing Control	Legal	Interested party concern	Likelihood	Severity	Risk Level	Significant/Non significant
1	2	3	4	5	6	7	8	9	10	11	12	13
	ASH POND	Earth excavation work(Manual)	Collapsing of earth	Injury / disability	R	EM-4/29,EM-4/36,EM-4/29	N	N	1	2	2	NS
			Falling into trench	Injury leading to fractures.	R	EM-4/79,EM-4/36,EM 4/43	N	N	1	2	2	NS
		Transportation of debris.	Faliure of vehicle due to over loading/unsafe driving/mechanical failure	Injury/Fatal	R	EM- 4/47,	N	N	1	1	1	NS
			Falling of dust in eye while loading & unloading	Eye irritation	R	EM-4/93,	N	N	1	2	2	NS
			Exposure to hazardous waste which are mixed with debris	Injury	R	EM-4/8	N	N	1	2	2	NS
		Ash pond works										
		(a) Re-built of slope	Hitting of excavator to dumper driver/helper/supervisor	Injury/Disability/Fatal	R	EM-4/36	N	N	1	3	3	NS
			Exposure to dust	Respiratory problem	R	EM-4/93,	N	N	1	2	2	NS
		(b) Turfing	Hiting of spade with body parts during cutting of turf by spade	Injury	R	EM-4/29,	N	N	1	2	2	NS
			Fall from slope of ash dyke during placing of turf	Injury	R	EM-4/36,EM-4/47	N	N	1	2	2	NS
			Fall from slope of ash dyke during watering to turf	Injury	R	EM-4/36,EM-4/47	N	N	1	2	2	NS
		(c) Stone pitching	Hiting of stone with body parts while unloading from dumper	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS

		Hiting of stone with body parts due	Turinom.	1	EM-4/47,EM-4/45	N	N	I		1	
			Injury		EM-4/4/,EM-4/45	N	IN				
		to fall of stone while carrying from		R				1	2	2	NS
		stack to work spot manually						_	_	_	
		Slip/Fall while carrying stone on	Injury/ disability/Fatal	R	EM 4/47	N	N	1	2	2	NS
		slope of ash dyke		11				-			110
		Hiting of stone with body parts	Injury	R	EM 4/47,EM-4/45	N	N	1	2	2	NS
		while placing stones		I.				1			110
		Slip/Fall while placing stone on	Injury/ disability	0	EM 4/47,EM-4/45	N	N	4	2	2	NG
		slope of ash dyke		R				1	2	2	NS
	(d) Supression of ash blowing	Exposure to dust while sprinklig	Physical Discomfort		EM-4/93,,EM-4/45	N	N				
		water	,	R	, , ,			1	1	1	NS
	Raising of ash pond	Water -									
	(a) Ash embankment construction engaging	Hitting of excavator to dumper	Injury/Disability/Fatal	NID	EM 4/47,EM-4/21	N	N	4	_	٠,	NIC
	machineries	driver/helper/supervisor		NR				1	2	2	NS
		Exposure to dust during unloading	Physical Discomfort		EM-4/93,EM-4/45	N	N				
			i nysicai Disconnoit	NR	EWI-4/93,EWI-4/43	11	11	1	1	1	NS
		of earth						_	_	_	
		Slipping/over topping of roller	Major injury/ Fatal		EM 4/47,EM-4/74,EM-	N	N		_	_	NIC
		during rolling		NR	4/21			1	3	3	NS
		Hitting by roller during rolling	Injury/Disability/Fatal	NR	EM-4/47,EM-4/74	N	N	1	3	3	NS
		0, 0		INIX	· ·				3	3	149
		Vehicle movement on narrow dyke	Injury/Disability/Fatal		EM-4/47,EM-4/74,	N	N				
		wall			Signage displayed,Traffic						
				NR	pole constructed near both			1	3	3	NS
				INIX	edge of the dyke for high			1	3	3	145
					visibility						
	(b) Earth embankment or earth covering	Hitting of excavator to dumper	Injury/Disability/Fatal		EM-4/74,EM-4/29	N	N				
	(-)	driver/helper/supervisor			.,,,						
		dirver/neiper/supervisor		R				1	3	3	NS
								_			
		Exposure to dust during unloading	Physical Discomfort		EM-4/93,,EM-4/45	N	N				
		of earth	Thysical Discomfort	R	EN 1753,,EN 1715	11	1,	1	1	1	NS
		Slipping/over topping of roller	Major injury/ Fatal	+	EM-4/74,EM-4/21	N	N				
			Major injury/ ratai	R	EMI-4//4,EMI-4/21	IN	IN	1	3	3	NS
		during rolling	T ' /D' 1''' /D : 1		EN 6 4/74 EN 6 4/01	3.7				1	1
		Hitting by roller during rolling	Injury/Disability/Fatal	R	EM-4/74,EM-4/21	N	N	1	3	3	NS
	(c)Sand blanket & chimney construction	Hitting by dumper during	Injury/Disability/Fatal	ND	EM-4/74,EM-4/21	N	N	1	2	2	NIC
		unloading sand		NR				1	3	3	NS
		Exposure to sand blown during	Physical Discomfort,Eye injury		EM-4/74,EM-4/21	N	N		_	_	
		transportation & unloading	,,,-, - , - , -	NR	, .,			1	3	3	NS
	(d)Inverted filter construction	Hiting of stone/boulder with body	Injury	+	EM-4/29,EM-4/74	N	N			 	
	(d)inverted inter construction		Injury	ND	Livi-4/27, Livi-4//4	14	IN	1	2	2	NS
		parts while unloading from dumper		NR				1	2	2	IND
├										<u> </u>	<u> </u>
		Hiting of stone/metal with body	Injury		EM-4/47,EM-4/45						
		parts due to fall of stone while		NR		N	N	1	2	2	NS
		carrying from stack to work spot		INIA		14	1,4	1			140
		manually									
		Slip/Fall while carrying	Injury/ disability/Fatal		EM 4/47	N	N				
		stone/metal/sand on slope of ash	3 3 3	NR				1	2	2	NS
		dyke		''''				-	1 -	~	1
		uyne								<u> </u>	1

	Hiting of stone/metal with body parts while placing stones	Injury	NR	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Slip/Fall while placing stone/metal /sand on slope of ash dyke	Injury/ disability	NR	EM-4/47,EM-4/45	N	N	1	2	2	NS
(e) Drain construction	Hiting of stone/boulder with body parts while unloading from dumper	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Hiting of stone/metal with body parts due to fall of stone while carrying from stack to work spot manually	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Slip/Fall while carrying stone/metal/sand and concrete on slope of ash dyke	Injury/ disability/Fatal	R	EM 4/47	N	N	1	2	2	NS
	Hiting of stone/metal with body parts while placing stones	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Slip/Fall while placing stone/metal /sand & concrete on slope of ash dyke	Injury/ disability	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
(f) Road construction	Hiting of construction materilas with body parts while unloading from dumpers	Injury	R	EM-4/47,EM-4/45,EM- 4/74	N	N	1	3	3	NS
	Hiting of stone with body parts due to fall of stone while carrying from stack to work spot manually	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Hiting of stone with body parts while placing stones	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Slipping/over topping of roller during rolling	Major injury/ Fatal	R	EM-4/74,EM-4/21	N	N	1	2	2	NS
	Exposure to dust while cleaning surface	Respiratory problems / Lung infection/	R	EM-4/93,,EM-4/45	N	N	1	1	1	NS
		Eye irritation	R	EM-4/45	N	N	1	2	2	NS
	Contact with hot material	Burn Injury	R	EM-4/45,EM 4/43	N	Y	1	2	2	NS
(g) Turfing	Hiting of spade with body parts during cutting of turf by sapde	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Fall from slope of ash dyke during placing of turf	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
	Fall from slope of ash dyke during watering to turf	Injury	R	EM-4/47,EM-4/45	N	N	1	2	2	NS
Stacking of construction materials at work site	Road accident due to dumping of construction material and work on road	Injury	NR	EM 4/47,EM-4/74,EM- 4/21	N	N	1	2	2	NS
Movement of Dumpers/Dozer/tractors/tankers & oth, heavy vehicles & light vehicles on ash pond dykes		Major injury/ Fatal	R	EM 4/47, EM 4/74, Effective supervision and training. Flaggers, Vehicle Speed control. Edge Guard Provision	N	N	1	3	3	NS
	Hitting by heavy vehicles & machinery during rolling	Injury/Disability/Fatal	R	EM-4/74,EM-4/21	N	N	1	2	2	NS

		Exposure to dust during movement	Physical Discomfort, Eye injury		EM-4/93,,EM-4/45	N	N				
		of vehicles/machineries		R	,			1	1	1	NS
		Exposure to noise<85db during running of vehicles	Physical Discomfort	R	EM-4/23,EM-4/45	N	N	1	2	2	NS
		Exposure to noise>85db during running of vehicles	Hearing impaired	R	EM-4/23,EM-4/45	N	N	2	2	4	NS
		Exposure to vehicular emission during working of heavy vehicles & machineries	Physical Discomfort,Eye injury	R	EM-4/74,EM-4/21	N	N	1	1	1	NS
Pa	ainting	Falling of objects from height	Injury	NR	EM-4/25,EM-4/45	N	N	1	3	3	NS
		Inhalation of fumes	Respiratory problems	NR	EM-4/47,EM-4/45	N	N	1	1	1	NS
		Falling from height	Injury	NR	EM 4/79, EM-4/47, MP- 08	N	N	1	3	3	NS
		Collapse/failure of scaffolding	Injury	NR	EM 4/7, 4/47, MP-08	N	N	1	3	3	NS
CI	leaning activities/Sanitary works	Exposure to dust	Respiratory problems	R	EM-4/93,,EM-4/45	N	N	1	1	1	NS
		Exposure to noise<85db	Physical discomfort	R	EM-4/23,EM-4/45	N	N	1	1	1	NS
		Exposure to noise>85 db	Hearing impairment	R	EM-4/23,EM-4/45	Y	N	1	2	2	NS
		Exposure to micro organisms / bacteria during cleaning or repair of toilets / urinals / pipelines	Health hazards due to infection	R	EM-4/41,EM-4/45,EM- 4/61	N	N	1	2	2	NS
	arth excavation work in shallow oundation/trenches	Collapsing of earth	Injury	R	EM-4/47,EM-4/36	N	N	1	2	2	NS
		Falling into trench	Injury leading to fractures	R	EM-4/47,EM-4/36,EM- 4/79	N	N	1	2	2	NS
Cc	oncreting at height	Fall from height	Injury	R	EM-4/7,EM-4/79,EM 4/43,MP-08	N	N	1	3	3	NS
		Failure of scaffolding	Injury	R	EM 4/7, MP-08	N	N	1	3	3	NS
		Falling of constructions materials	Injury	R	EM 4/47	N	N	1	2	2	NS
		Exposure to dust	Respiratory problems	R	EM-4/93,,EM-4/45	N	N	1	1	1	NS
		Contact with concrete	Skin irritation	R	EM-4/45	N	N	1	1	1	NS
Gr	rass cutting	Snake bite by poisonous snake	Fatal	R	EM 4/43,EM-4/45	N	N	1	3	3	NS
		Contact with vegetation	Skin irritation	R	EM-4/45	N	N	1	1	1	NS
		Thorn prick	Injury	R	EM-4/29	N	N	1	1	1	NS
Tr	ransportation of debris	Faliure of vehicle due to overloading/unsafe dtiving /mechanical failure	Accident	R	EM 4/45	N	N	1	3	3	NS
		Falling of dust in eye while loading & unloading	Eye irritation	R	EM-4/93,,EM-4/45	N	N	1	2	2	NS